



718 3rd Street Eureka, California Ph: (707) 443-8326 Fax: (707) 444-8330	Contact Name:	Scott Harris, Matt Tolley	Sample Date:	5/29/2019
	Contact Email:	scott.harris@ghd.com, matt.tolley@ghd.com	Client:	HSU
	Analysis Method:	PLM (Asbestos) - please provide result for each layer where multiple materials exist	Site:	Gist Hall Attic
	Turnaround Time:	RUSH - 8-HOUR ANALYSIS	Project #:	11195984.01

11195984.01

Sample Number	Sample Description	Location	USEPA Material Type	Friability
11195984-ATTIC-1	3" O.D. Pipe Insulation (yellow) + Fibrous Backing (white)	Basement - Above Drop Ceiling, Hot Water Supply Run - West side at 3" O.D. pipe run	TSI	F
11195984-ATTIC-2	3" O.D. Pipe Insulation (yellow) + Fibrous Backing (white)	Basement - Above Drop Ceiling, Hot Water Return Run - West side at 3" O.D. pipe run	TSI	F
11195984-ATTIC-3	Blown-in Insulation (yellow, fiberglass)	East Attic - Floor at south-SW (N of TSI run)	TSI	F
11195984-ATTIC-4	Blown-in Insulation (gold/pink, fiberglass)	Center-South Attic - Floor at SE corner (S of TSI run)	TSI	F
11195984-ATTIC-5	Blown-in Insulation (pink, fiberglass)	Center-South Attic - Floor at NW corner (N of TSI run)	TSI	F
11195984-ATTIC-6	Blown-in Insulation (pink, fiberglass)	Center-South Attic - Floor at SW corner (S of TSI run)	TSI	F
11195984-ATTIC-7	Blown-in Insulation (pink, fiberglass)	Center-South Attic - Floor at NE corner (N of TSI run)	TSI	F
11195984-ATTIC-8	Blown-in Insulation (gold/pink, fiberglass)	West Attic - Floor at SW corner at (N of vert TSI run)	TSI	F
11195984-ATTIC-9	Blown-in Insulation (pink, fiberglass)	East Attic - Floor at center-N (S of TSI run)	TSI	F
11195984-ATTIC-10	Blown-in Insulation (pink, fiberglass)	East Attic - Floor at SW corner (N of TSI run)	TSI	F
11195984-ATTIC-11	Blown-in Insulation (gold/pink, fiberglass)	Center West - Floor at center-S (N of TSI run)	TSI	F
11195984-ATTIC-12	Blown-in Insulation (pink, fiberglass)	Center West - Floor at center (E of horizontal TSI run)	TSI	F

Released by:
Date/time:
www.ghd.com

Received by:
Date/time:
www.ghd.com



718 3rd Street Eureka, California Ph: (707) 443-8326 Fax: (707) 444-8330	Contact Name:	Scott Harris, Matt Tolley	Sample Date:	5/29/2019
	Contact Email:	scott.harris@ghd.com, matt.tolley@ghd.com	Client:	HSU
	Analysis Method:	PLM (Asbestos) - please provide result for each layer where multiple materials exist	Site:	Gist Hall Attic
	Turnaround Time:	RUSH - 8-HOUR ANALYSIS	Project #:	11195984.01

11195984.01

Sample Number	Sample Description	Location	USEPA Material Type	Friability
11195984-ATTIC-13	Remnant TSI (yellow, fiberglass) + foil cover (white, silver)	West Attic - Floor at TSI remnant at center	TSI	F
11195984-ATTIC-14	Coating/paint remnant (off-white, grey)	East Attic - North at center-NW	TSI	F

Released by:
Date/time:
www.ghd.com

Received by:
Date/time:
www.ghd.com